## CONTROL SURVEY MONUMENT RECOVERY

Cathedral City

Date Printed: 10/01/2003

Number: **1005** Name: **TP-1005** 

Monument Description: G	SPS Useable:	
Set concrete nail		
Stamping:		
Center Mark:		
Recovery By: RBF	Date: Mar 1997	
Location:		
On an electrical system r		
northeaserly corner of Landau and Vista Chino		
50 ft northerly of Vista Ch	nino and 100 ft easterly of	
Landau	into and 100 it casterly of	
Notes:		

NAD 83	Coordina	ites	Epoch:	Accuracy:	S	Survey by:	Adj.:
Ellipsoidal Coordinates, GRS 80			Horizontal Co	ordinates	CCS 83, Zone 6 Coordinates		
	Deg.	Min	. Seconds			Meters	US Survey Feet
Latitude					Northin	g:	
Longitude					Easting	g:	
Ellipse Height (m):					Grid Scale:		
						Height Scale:	
						Combined Factor:	

Elevation (MSL)	Meters	Feet	Epoch Date	Survey By	Adj. Date	Accuracy
NAVD88:	127.656	418.820	1991.5	RBF	March 1997	Second, I
NGVD29:		416.490		RBF	March 1997	Second, II